Work Order #	Location	Work Requsted
2019-01	Holman Road	Request road scraped
2019-02	Concord By Way/Concord Road	Request road scraped
2019-03	Johnny Fears Road	Request work on pot holes
2019-04	Dulin Ct	Request work on pot holes/washout
2019-05	Palalto Road	Request work on road horrible shape
2019-06	Wicker Road	Request gravel
2019-07	Davis Road	Request work on pot holes
2019-08	Herds Creek Road	Request road scraped
2019-09	Jackson Lake Road	Request road sign Bus Stop Sign/Child At Play
2019-10	Aldridge Road	Request work on road horrible shape
2019-11	Marben Farms Road	Request gravel
2019-12	97&111 Herring Gull	Request gravel
2019-13	Wendy Hill Road	Request work on big pot hole
2019-14	26 Mack Tillman Drive(Senior Center)	Request tire service on 2009 Passenger Van
2019-15	Murder Creek	Request gravel
2019-16	Johnny Fears Road	Request work on pot holes
2019-17	Pauline St & Miss Sarah	Request work on drainage issue
2019-18	Holman Road	Request culvert
2019-19	Bobolink Ct	Request work on pot holes
2019-20	Parrot Ct	Request Stop sign
2019-21	Flamingo Dr	Request Speed Limit sign put back up
2019-22	Holloway Hollow Road	Request road scraped and gravel
2019-23	Marben Farm&Concord Road	Request work on pot holes, scraped, gravel or asphalt
2019-24	Raven Road	Request work on pot holes
2019-25	Cook Road	Request drainage ditch cleaned
2019-26	Holman Road	Request ditches/pipes cleaned
2019-27	Doe Lane	Request culvert installed
2019-28	Wild Road	Request work on pot holes
2019-29	Marben Farm Road	Request road scraped
2019-30	Bluejay Ct	Request work on pot holes
2019-31	Herds Creek Road	Request road scraped
2019-32	Lloyd Cemetary Road	Request road scraped
2019-33	Kline Road	Request culvert cleaned out

2019-34	Wild Road	Request work on pot holes
2019-35	Bunting Ct	Request culvert cleaned out
2019-36	50 Meadowlark	Request work at driveway bad washout
2019-37	86 Stag Run Road	Request culvert cleaned out
2019-38	Jordan Road	Request road scraped
2019-39	Oconee Forest Road	Request road scraped
2019-40	Shephard Road	Request road scraped
2019-41	Wehunt Road	Request gravel
2019-42	Bragg Road	Request road scraped
2019-43	Marben Farm Road	Request work on pot holes
2019-44	Smithmill Road	Request road scraped
2019-45	Allen Road	Request road scraped
2019-46	Redtail Ct	Request road sign No TURN AROUND
2019-47	Wild Road	Request work on pot holes
2019-48	Holloway Hollow Road	Request work on pot holes
2019-49	Williams Road	Request road scraped
2019-50	New Bethel Grove	Request road scraped
2019-51	Alridge Road	Request road scraped
2019-52	Armour Road	Request gravel
2019-53	Alexander Road	Request road scraped
2019-54	Post Road (Tennis Court)	Request drainage ditch cleaned
2019-55	Herds Creek Road	Request work on pot holes
2019-56	26 Mack Tillman Drive(Senior Center)	Request work on power steering 2008 Passenger Van
2019-57	Meadowlark Drive	Request road scraped
2019-58	Bobby Mattison Road	Request road scraped
2019-59	Bear Creek Point	Request work on bad wash out
2019-60	Cook Road	Request road scraped
2019-61	Raby Road	Request work on road horrible shape
2019-62	Felton McMichael Road	Request work on road horrible shape
2019-63	695-885 Hughes Road	Request work on road horrible shape
2019-64	Midway Church Road	Request gravel
2019-65	252 Whispering Pine	Request work on driveway drainage problem(no ditches)
2019-66	Lane Road	Request drainage pipe installed
2019-67	Smithmill Road	Request drainage pipe installed

2019-68	1023 Turner Road	Request gravel
2019-69	Armour/Wehunt Road	Request ditches pulled
2019-70	1207 Wehunt Road	Request work on driveway bad pot hole
2019-71	Alexander Road & Second half of Blacky	v Request road scraped
2019-72	Post Road	Request work before bridge shoulder edge breaking
2019-73	Post Road	Request work on pot hole at bridge
2019-74	Herds Creek Road	Request dumping moved at bridge(tires)
2019-75	Smithmill Road	Request road scraped and gravel
2019-76	Cook Road	Request gravel
2019-77	ChickADee Ct	Request work on pot holes
2019-78	Palalto Road	Request road scraped
2019-79	Bullard Road	Request road scraped